


**VFP1 PIPE SCHEMATIC**



**NOTE:**  
 Pipe schematic for Discharge Pipes drawn as if standing in the VFP1 spillway looking easterly towards the Discharge Pipes. Flush Pipes drawn as if standing in the FP looking south-westerly towards the Flush Pipes.

**VFP2 PIPE SCHEMATIC**



**NOTE:**  
 Pipe schematic for Discharge Pipes drawn as if standing in the VFP2 spillway looking easterly towards the Discharge Pipes. Flush Pipes drawn as if standing in the bottom of SP2 looking north-westerly towards the Flush Pipes.



**DE SALE RESTORATION AREA - PHASE III**  
 Stream Restoration Incorporated  
 Venango Township, Butler County, PA  
 January 2007, Scale 1" = 60'

