




SR81 ABANDONED MINE RESTORATION AREA

SITE SCHEMATIC
Slippery Rock Watershed Coalition

in cooperation with
Stream Restoration Incorporated
State Game Lands No. 95
Washington Township, Butler County, PA
June 2004, Scale 1" = 60'



SITE MAP

1" = 600'

