Slippery Rock Watershed Coalition NORTH LIBERTY RECLAMATION AREA PHASE I & II FACT SHEET

Liberty Township, Mercer County, PA

Amerikohl Mining Inc.	Agnes Lapa
David and Linda Beatty	Mercer County Conservation District
BioMost, Inc	PA DEP, Knox District Mining Operations
Brenner Ecological	Slippery Rock Watershed Coalition
George Junior Republic	Stream Restoration Incorporated
Grove City College	Urban Wetland Institute

COMPLETION DATE:

Major construction completed October 2001; Water Quality Monitoring ongoing by PA DEP, Knox DMO

Site History: A 40+ acre surface coal mining operation was previously conducted by the Bowie Coal Company in the 1940's. The site was only partially reclaimed by planting trees on the spoil piles, which was successful, but much of the site including about 15 acres of water-filled open pits and 1300 linear feet of 50 foot highwalls were left unreclaimed. Two of the larger water-filled pits were located dangerously close to Courtney Mill Road, a public road. One of the pits and associated highwall was located only about 250 feet from a historic farmhouse.

PROJECT SUMMARY:

- Pumped and treated over 7 million gallons of degraded water from 4 large abandoned pits;
- Incorporated 580 tons of alkaline material (Reclime) to neutralize existing acid-producing spoils during backfilling of ~15 acres of open pits with 1300 linear feet of highwalls, with a maximum highwall height of ~60 feet;
- Restored ~43 acres of abandoned mine lands to productive farmland, which was characterized by spoil
 piles, dangerous highwalls and water-filled pits with degraded drainage for 50+ years;
- Planted 51 trees (Blue Spruce and Norway Spruce) around the historic farm house (2nd oldest dwelling in Mercer Co.) to serve as a windbreak;
- Planted ~3000 wetland plants with adjudicated youth from George Junior Republic to provide wildlife habitat.

Reference	Sampling Point	Lab pH	Alkalinity	Acidity	Fe	Mn	AI
	Pit #1	4.80	6	142	41	9	4
Pre-restoration	Pit #2	3.53	0	271	7	27	30
	Pit #3	2.88	0	281	12	6	21
	Pit #4	3.10	0	134	12	4	7
Post-restoration	Settling Basin #1	6.92	36	0	1	<1	1
	Settling Basin #2	7.23	48	0	<1	1	<1

WATER QUALITY (representative):

FUNDING SOURCE:

Commonwealth of Pennsylvania "Growing Greener program; contributions from project partners